

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	David Shaver Manager					
OGM	Karl Houskeeper Environmental Scientist III					

Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Thursday, February 05, 2009
Start Date/Time:	2/5/2009 9:00:00 AM
End Date/Time:	2/5/2009 1:00:00 PM
Last Inspection:	Tuesday, January 20, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 35 Deg. F.

InspectionID Report Number: 1907

Accepted by: jhelfric

3/11/2009

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC

Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

6,235.80	Total Permitted	✓ Federal	✓ Underground
27.15	Total Disturbed	☐ State	Surface
	Phase I	☐ County	Loadout
	Phase II	☐ Fee	Processing
	Phase III	☐ Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Thursday, February 05, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, February 05, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		~	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				. 🗆
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, February 05, 2009

Page 3 of 3

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

Diversions are snow covered as is the majority of the mine site.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond is still being pumped. The water elevation has been lowered since the previous inspection.